



شركة ريسوت للإسمنت  
Raysut Cement Company



# MONTHLY MAGAZINE

A magazine specialized in the news of Raysut Cement Company



[www.raysutcement.om](http://www.raysutcement.om)



Dear All

we are grateful that, despite widespread economic disruption we are still able to push on with our ambitious growth plan to reach our vision and all of this because of the passion of our executive management and employees in the RCC group who are continuously exploring and experimenting in new ways of working that sustain us.

we will keep our concentrate on raising our growth in many different areas locally and globally to be the pioneer organization in our field.

Wishing everyone good health and happiness




### CEO Message



شركة ريسوت للإسمنت  
Raysut Cement Company

## WHRS Plant Progress Report - Feb 2022 - RCC Salalah

SN	AREA	REINFORCED CONCRETE			Structure Steel MT			St & Mechanical		
		EST	PCC Comp	RCC Comp	Civil St	Comp	%	Est. MT	Comp	%
1	STG BUILDING	800	119	789	18	10.411	58%	140	116.8	83%
1A	Turbine & Generator	106	---	---	---	---	---	---	---	---
2	CHEMICAL WATER TR PLANT	256	16	144	2	2	100%	50	52	103%
3	AIR COOLED CONDENSER	433	39	393	13	3.572	27%	218	217.2	100%
4	LINE -2 AQC BOILER	135	19	132	22	---	0%	226	153	68%
5	LINE-2 SP BOILER	150	7	138	12	1.283	11%	180	109	60%
6	LINE -3 AQC BOILER	93	11	83	15	7.8	52%	247	240	97%
7	LINE-3 SP BOILER	267	9	233	44	16.5	38%	400	385.1	96%
8	LINE-4 AQC BOILER	181	7	132	30	22.0	73%	290	138.2	48%
9	LINE-4 SP BOILER	400	96	291	42	0.713	2%	289	164.925	57%
10	COOLING WATER SYSTEM	89	14	192	1	1	100%	100	48.9	49%
11	RAW WATER SYSTEMS	---	---	---	---	---	---	---	0.415	---
12	BDT & N-PIT	83	15	90	2	2	100%	4	0.369	---
13	OUTDOOR PIPING, STRUCTURE	131	6	35	31	12.2	39%	200	72.696	36%
TOTAL		3124	358	2652	232	79.6	34%	2344	1698	72.5%



### New Hydra Crane Purchased for RCC - Salalah Plant : The Pick & Carry 15T Escort Hydra

Pick & Carry crane will improve the efficiency of handling of material, will save time and will be safer. It will help in reducing downtime of the equipment, its more approachable in narrow areas, and for weight of material till 10 Tons, big crane (50T XCMG) will not be required., as more material can be quickly moved around the job site.





## Raysut Cement Company Exports - February

## 2022 PRODUCTWISE EXPORTS- FEB

PRODUCT	MT
PLC BULK	34,044.71
PLC BAGS	47,407.50
OPC BULK	15,839.93
OPC BAGS	8,325.15
SRC BAGS	1,637.50
SRC BULK	620.25
TOTAL- CEMENT	107,875.04
CLINKER	44,000.00

## 2022 / COUNTRYWIDE EXPORTS -FEB

COUNTRY	MT
YEMEN	20,706.86
SOMALIA	40,043.18
Seychelles	280.00
INDIA	550.00
Reunion	7,100.00
Tanzania	31,000.00
MALDIVES	8,195.00
TOTAL-CEMENT	107,875.0
CLINKER /REUNI	44,000.00



## Commercial

- ▶ Recorded M-o-M growth of %17 in Feb'22 with a volume of 8,740 tons in spite of limited stock availability.
- ▶ Sales recorded in Jan-Feb'22 is 23,797 tons which is a growth of %130 Y-o-Y.



## Business Development

- ▶ Won supply contracts and started supplies for Water and Sewerage Projects in over 34 islands from Indian Contractors, SMC, JMC India and Vishvaraj.
- ▶ In final discussion for product approval with Afcons for the Thila-Male' bridge mega infrastructure project.
- ▶ Extending support to Mohan Muhtha Exports and Jyoti Impex for their infrastructure projects



New service

- The new internet and fixed-line service started at Sohar Cement Factory with the new operator, Oman Telecommunications Company (Omantel)



مصنع إسمنت صحر  
SOHAR CEMENT FACTORY

## Training

- ▶ During February fire training was undertaken at our sites to refresh our employees on the Safe use of Fire Extinguishers this training is invaluable not only in the workplace but can be used in the home environment.

Environment Authority Salalah will work with RCC to deliver a suite of training to new Environmental Authority employees.

The suite of training will include the following:

- Laws and Regulations
- Waste Management
- Ambient Air Quality Management
- Stack Emissions and Abatement



Delivering Fire Training to Head Office Team

## 2022 Training Plan

- ▶ The 2022 training plan has been submitted to HR most of the training will be undertaken in-house with some specialist training outsourced due to regulatory and/or other requirements

## Development

- ▶ The three Safety Professionals are now embarking on Diploma NVQ Level 6 - we wish all the candidates every success in working towards achieving this qualification.

## Security

- ▶ The new security procedures have been sent to all BU's for implementation and are available on one drive for anyone who requires them.



## Accidents and Incidents

- ▶ During the month of February we are pleased report that there were no injuries in any of our facilities.

There was one incident at the quayside in Maldives where a mooring rope broke action was taken immediately to inspect and replace danmaged all ropes, this task has now been

Target TRIR	≤4
Target LTIFR	≤0.5
TRIR	3.29
LTIFR	1.32

The LTIFR and TRIR targets have been reduced from 2021 LTIFR ≤0.75 and TRIR ≤5 this is a steady progression to reach the goal of Zero Incidents.

## One Drive

- ▶ We continue to upadet the HSSE Folder in One Drive to give access to all our employees, we have recently updated all Safety, Covid19 and Security documents.

One drive is the central library for all our information and we encourage departments to upload their HSE Risk Assessments and Standard Operating Procedures in this portal.

## Workplace Safety Rules

- ▶ Taking actions to ensure that employees have a safe workplace is a top priority for every employer. This includes communicating workplace safety with employees.

There are 10 rules to adhere to when it comes to workplace safety:

1. Everyone is responsible for safety
2. Wear appropriate Personal Protective Equipment - as required by the job
3. Ensure workspaces are tidy
4. Follow all safety rules
5. Immediately report accidents and incidents
6. Understand and follow any emergency procedures and ensure you know location of emergency equipment - Fire Extinguishers, Pull Cords Stop Buttons and First Aid Kits
7. Take care with lifting and bending
8. Only operate equipment you've been trained to use
9. Ensure you replace all guards and safety devices at end of each job
10. If you observe anything that is unsafe report it immediately to Supervisor, Manager or HSSE

## Gate Passes

- ▶ The new gate pass system is full implemented at RCC, Sohar and Pioneer with the numbers of employees leaving the BU's dropping by over %70.
- ▶ Managers must ensure gate passes are only issued against the specific criteria in the procedure and follow up with HR when employees don't return to BU after receiving gate passes

## Covid19

- ▶ As the protective measures and rules are relaxed everyone must be aware that Covid19 has not went away and we should continue to protect ourselves and our families by implementing the new rules and if required to go further to keep ourselves and our families safe.
- ▶ The sterilization lane in Raysut Cement has been updated with a new look





# SULPHATE RESISTING PORTLAND CEMENT

## إسمنت بورتلاندي مضاد للأملاح



### إسمنت بورتلاندي مضاد للأملاح :

هو إسمنت مضاد للأملاح يستخدم لأغراض البناء في المناطق الساحلية والمناطق التي تحتوي فيها التربة القلوية والمياه الجوفية على كميات عالية من الكبريتات .

### SULPHATE RESISTING PORTLAND CEMENT

Sulfate resistant Portland cement is used for construction purposes in the areas where it contains Alkaline soil and groundwater contain high amounts of sulfate .



Made in Oman

ملتزمون بالجودة,,  
We Guarantee Quality



شركة ريسوت للإسمنت  
Raysut Cement Company

[www.raysutcement.com.om](http://www.raysutcement.com.om)